



Tnemec Company, Inc.  
 123 West 23rd Avenue, Kansas City, MO 64116-3064  
 Emergency Telephone: 800-535-5053 (INFOTRAC)  
 Telephone: 816-474-3400

## Material Safety Data Sheet (MSDS)

For coatings, resins and related materials, approved by the U.S. Department of Labor as essentially similar to form OSHA-20, meets requirements of CFR 29 Part 1910.1200, OSHA'S hazard communication standard.  
 NPCA 1-84

PREPARED DATE: 11/02/2006 Series: L-69-1203A Product Class: POLYAMINE AMIDO AMINE HB EPOXOLINE II L-69 WHITE Page 1 of 2

### SECTION 2 - HAZARDOUS INGREDIENTS

INGREDIENTS	CAS#	% By Wt.	VAPOR PRESS. MMHG @ 68 °F	OCCUPATIONAL EXPOSURE LIMITS					
				ACGIH			OSHA		
				TLV - TWA	TLV - STEL	TLV - C	PEL - TWA	PEL - STEL	PEL - C
CRYSTALLINE SILICA (QUARTZ)	14808-60-7	14.76		0000.025 MG/M3			0000.050 MG/M3		
TITANIUM DIOXIDE (TOTAL DUST)	13463-67-7	11-20		0010.000 MG/M3			0010.000 MG/M3		
TALC (RESPIRABLE DUST)	14807-96-6	21-30		0002.000 MG/M3					
AMORPHOUS SILICA	7631-86-9	1-5		0010.000 MG/M3			0006.000 MG/M3		
ALUMINUM OXIDES	1344-28-1	1-5		0010.000 MG/M3					
MODIFIED CYCLOALIPHATIC POLYAMINE ISOPHORONE DIAMINE	2855-13-2	6-10 1-5		0000.100 MG/M3 MFG REC					
N-BUTANOL (SKIN)**	71-36-3	4.17	4.400	0020.000 PPM		0050.000 PPM	0100.000 PPM		0050.000 PPM
BENZENE, 1-CHLORO-4-(TRIFLUOROMETHYL)-	98-56-6	17.25							

#### \*\* SARA Reportable Product

This product contains one or more reported carcinogens or suspected carcinogens which are noted NTP, IARC, or OSHA-Z in the other limits recommended column. This product contains pigment dusts which may be released when subjected to abrasive blasting, sanding, or grinding. The information contained in this section is considered confidential and proprietary and should be used only for safety and health purposes.

### SECTION 3 - HEALTH HAZARD INFORMATION

EMERGENCY OVERVIEW: POTENTIAL HEALTH EFFECTS: EYE: Severe irritation. Redness, tearing, blurred vision. Corrosive responses, burns. SKIN: Severe burns. Can be a skin sensitizer. INHALATION - OVEREXPOSURE TO SOLVENT VAPORS OR SPRAY MIST: Severe burns. Severe nasal and respiratory tract irritation. May cause allergic respiratory reaction. INHALATION - OVEREXPOSURE TO FREE PIGMENT DUST: Coughing, wheezing, shortness of breath, restricted nasal passages, lung injury. INGESTION: Gastrointestinal irritation, nausea, vomiting, diarrhea, death, aspiration into the lungs which can be fatal. Corrosive responses and possible burns to the gastrointestinal tract. CHRONIC EFFECTS: Prolonged inhalation of dusts containing crystalline silica may result in the development of a lung disease known as silicosis. NOTICE: Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the vapors may be harmful or fatal. Prolonged or repeated contact with skin may cause primary irritation, dermatitis, or allergic skin reactions. This product contains crystalline silica, which is considered a cancer hazard by inhalation of respirable dust. The International Agency for Research on Cancer (IARC) concluded that respirable crystalline silica inhaled in the form of quartz or cristobalite from occupational sources is carcinogenic to humans (Group 1B). TARGET ORGANS: Can be corrosive to eyes. Can cause respiratory tract irritation. Can be corrosive to skin. Can cause lung damage. Can cause liver damage. Can cause cancer. Risk of cancer depends on duration and level of exposure. Can cause respiratory tract sensitization. Can be corrosive to gastrointestinal tract. Can cause kidney damage. Can cause nervous system effects. Can cause skin sensitization. OTHER: This product when mixed with other components acquires the hazards of all components. PRIMARY ROUTES OF ENTRY: Dermal and Inhalation. PROPOSITION 65: Pigments and/or other raw materials present in this product contain trace amounts of a chemical or chemicals known to the State of California to cause cancer, birth defects or other reproductive harm.

### SECTION 4 - FIRST AID MEASURES

EYE CONTACT: Flush immediately with large amounts of clean water under low pressure for at least 15 minutes. Consult a physician. SKIN CONTACT: Wash affected area with soap and water. Remove contaminated clothing. Dispose of or launder accordingly. Consult a physician if skin irritation persists. INHALATION: Remove affected individual to fresh air. Treat symptomatically. If breathing is difficult, administer oxygen. If breathing has stopped give artificial respiration. Consult a physician. INGESTION: Drink 1 or 2 glasses of water to dilute. Do not induce vomiting. Consult a physician or poison control center IMMEDIATELY. Treat symptomatically. NOTE TO PHYSICIAN: Exposure may aggravate persons with eczema, skin sensitization, or other chronic skin disorders and allergies.

**SECTION 5 - FIRE AND EXPLOSION HAZARD DATA**

FLAMMABILITY CLASSIFICATION	FLASHPOINT	EXPLOSION LEVEL LOW	EXPLOSION LEVEL HIGH	FLAMMABILITY LIMITS LOWER	FLAMMABILITY LIMITS HIGHER
	105.0 °F	1.4	-N/A	-N/A	-N/A

EXTINGUISHING MEDIA: Foam, carbon dioxide, and dry chemical. FIRE-FIGHTING PROCEDURES AND EQUIPMENTS: Keep away from heat, open flames, sparks, and areas where static charge may be generated. Do not apply to hot surfaces due to possible fire and explosion risk. For closed containers, pressure build-up and possible explosion might occur due to extreme heat exposure. Solvent vapors are heavier than air and may travel considerable distance to a source of ignition and flash back. Water may be used to cool unruptured containers. Wear self-contained breathing apparatus with a full facepiece operated in pressure-demand or other positive pressure mode to prevent inhalation of hazardous decomposition products. Use appropriate extinguishing media to control fire. Water may cause violent frothing if sprayed directly into containers of burning liquid.

**SECTION 6 - SPILL OR LEAK PROCEDURES**

Remove all sources of ignition. Spills may be collected with inert, absorbent material for proper disposal. Use non-sparking tools, protective gloves, goggles and clothing, adequate ventilation, avoid the breathing of vapors and use respiratory protective devices. Transfer absorbent material to suitable containers for proper disposal. CLEAN-UP:

**SECTION 7 - SPECIAL PRECAUTIONS**

HANDLING AND STORAGE: Store in dry area. Keep closures tight and upright to prevent leakage. Do not store in high temperature areas or near fire or open flame. Refer to product data sheet for recommended storage temperatures. SPECIAL COMMENTS: Prevent prolonged breathing of airborne contaminants such as vapor, spray mists, or dusts. Prevent contact with skin and eyes. Do not take internally. Keep out of reach of children. Do not reuse or alter containers without proper industrial cleaning. Do not weld or flame cut empty, uncleaned containers due to potential fire and explosion hazard. Consult product data sheet for proper application instructions.

**SECTION 8 - SAFE HANDLING AND USE INFORMATION**

HYGIENIC PRACTICES: Wash hands and other contaminated skin areas with warm soap and water before eating. EYE PROTECTION: Use chemical resistant splash type goggles. RESPIRATORY PROTECTION: Respiratory protective devices must be used when engineering and administration controls are not adequate to maintain Threshold Limit Values (TLV) and Permissible Exposure Limits (PEL) of airborne contaminants below the listed values for those hazardous ingredients identified in Section II of this MSDS. Observe OSHA regulations for respirator use (CFR 29, 1910.134) whenever a respirator is used. Particulate, chemical cartridge, air purifying half-mask respirators can be used within certain limitations; consult the respirator manufacturer for specific uses and limitations. Where airborne contaminant concentrations are unknown, the use of a NIOSH/MSHA approved fresh-air supplied respirator is mandatory. OTHER PROTECTION: Use Chemical resistant gloves. Use chemical resistant coveralls or apron to protect against skin and clothing contamination. Use protective cream where skin contact is likely. VENTILATION: Sufficient ventilation, in volume and pattern, should be provided through both local and general exhaust to keep the air contaminant concentration below current applicable OSHA Permissible Exposure Limits (PEL) and ACGIH's Threshold Limit Values (TLV). Appropriate ventilation should be employed to remove hazardous decomposition products formed during welding or flame cutting operations of surfaces coated with this product. Heavier than air solvent vapors should be removed from lower levels of work area due to potential explosion hazard and all ignition sources (non-explosion proof equipment) should be eliminated if flammable mixtures will be encountered.

**SECTION 9 - PHYSICAL AND CHEMICAL PROPERTIES**

VAPOR PRESSURE	VAPOR DENSITY	LOWER BOILING RANGE	HIGHER BOILING RANGE	FORMULA WEIGHT BY VOLUME	VOC IN LBS PER GALLON	EVAPORATION RATE	%VOLATILE BY WEIGHT
4.40	-N/A	241.0 °F	245.0 °F	14.7300 LB/GL	1.282	19.600 (Ether = 1)	14.130

**SECTION 10 - STABILITY AND REACTIVITY**

INCOMPATIBILITIES: Strong oxidizing agents. Bases. Acids. DECOMPOSITION: Carbon monoxide, carbon dioxide, hydrocarbon fragments Hydrogen chloride. Hydrogen Fluoride and Organic Halides. CONDITIONS TO AVOID: Epoxy compounds under uncontrolled conditions. Heat, sparks, open flames. POLYMERIZATION: Will not occur. STABILITY: Stable.

**SECTION 13 - DISPOSAL CONSIDERATIONS**

WASTE DISPOSAL: Dispose of in accordance with Federal, state, and local regulations regarding pollution.

**SECTION 16 - HMIS INFORMATION**

Health: 2                      Flammability: 3                      Reactivity: 1

This is a condensed MSDS, providing safety and health information pertinent to the complete product series. Physical constants such as Wt./Gal., VOC content and chemical constituents will vary with color. Safety and health information may also vary with color. Certain colors may contain Carbon Black and Crystalline Silica, which have been identified as reported or suspected carcinogens. Prolonged inhalation of respirable dusts containing Crystalline Silica may result in the development of a lung disease known as silicosis. For a complete, color-specific MSDS, please contact your local Tnemec representative listed at [www.tnemec.com](http://www.tnemec.com).

For specific information regarding occupational safety and health standards, please refer to the Code of Federal Regulations, Title 29, Part 1910. To the best of our knowledge, the information contained herein is accurate. However, neither the Tnemec Company or any of its subsidiaries assume any liability whatsoever for the accuracy or completeness of the information contained herein. Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown health hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards which exist.